

Recommended cutting conditions


Material	m/min Cutting speed	mm/tooth Feed rate	ø8		ø10		ø12			
			min ⁻¹	mm/min	min ⁻¹	mm/min	min ⁻¹	mm/min		
Carbon Steels Alloy Steels (30 HRC)	100-200	0,2-0,3	6370	2550	5090	2040	4240	1700		
			Vc=160m/min fz=0,2mm/tooth ap=0,025D ae=0,1D							
Carbon Steels Alloy Steels (30-40 HRC)	80-150	0,2-0,3	4770	1910	3820	1530	3180	1270		
			Vc=120m/min fz=0,2mm/tooth ap=0,025D ae=0,1D							
Die Tool Steels Pre-Harden Steels (30-40 HRC)	70-100	0,1-0,15	3180	640	2550	510	2120	420		
			Vc=80m/min fz=0,1mm/tooth ap=0,025D ae=0,1D							
Hardened Steels (55-65 HRC)	200-250	0,2-0,4	9150	3660	7320	2930	6100	2440		
			Vc=230m/min fz=0,2mm/tooth ap=0,01D ae=0,02D							
Cast Iron	100-200	0,3-0,4	6730	3820	5090	3050	4240	2550		
			Vc=160m/min fz=0,3mm/tooth ap=0,025D ae=0,1D							

Material	m/min Cutting speed	mm/tooth Feed rate	ø16		ø20		ø25		ø30(32)	
			min ⁻¹	mm/min	min ⁻¹	mm/min	min ⁻¹	mm/min	min ⁻¹	mm/min
Carbon Steels Alloy Steels (30 HRC)	100-200	0,2-0,3	2400	1600	2550	1300	2050	1030	1700	850
			Vc=160m/min fz=0,25mm/tooth ap=0,05D ae=0,1D							
Carbon Steels Alloy Steels (30-40 HRC)	80-150	0,2-0,3	1600	1200	1910	955	1530	765	1280	640
			Vc=120m/min fz=0,25mm/tooth ap=0,05D ae=0,1D							
Die Tool Steels Pre-Harden Steels (30-40 HRC)	70-100	0,1-0,15	3200	385	1280	310	1020	245	850	205
			Vc=80m/min fz=0,12mm/tooth ap=0,05D ae=0,1D							
Hardened Steels (55-65 HRC)	200-250	0,2-0,4	4575	2740	3660	2200	2930	1760	2440	1460
			Vc=230m/min fz=0,3mm/tooth ap=0,01D ae=0,02D							
Cast Iron	100-200	0,3-0,4	3200	2240	2550	1790	2050	1440	1700	1190
			Vc=160m/min fz=0,35mm/tooth ap=0,05D ae=0,1D							

Note

- According to the machining situation, refer to the table above to determine the cutting conditions.
- Be sure to practice safety instructions and precautions such as wearing glasses and safety shoes, and placing safety covers when you use this tool.
- Because this tool can be broken during machining so failure to follow these instructions may cause personal injury.
- Never attempt to modify the carbide shank holder. Use the value for the depth of cut (ap) when the carbide shank holder is used.
- Mill diameters D=8~12mm:ap<=0,2mm.
- Mill diameters D=16~32mm:ap<=0,3mm.

$$n = \frac{V_c \cdot 1000}{\pi \cdot \text{Def.}} \text{ (Rev/min)}$$



N = Spindle speed (Rev/min.)
 Vc = Cutting speed
 Def. = Effective cutting diameter
 ap = Max. Depth of cut (mm)

